



Photo 1: View of the project area from the southwestern corner of the well pad facing center.



Photo 2: View of the southern portion of the project area from the southwestern corner of the well pad facing eastward.



Photo 3: View of revegetation within the southwestern portion of the project area from the southwestern corner of the well pad facing westward.



Photo 4: View of erosive channel occurring along the access road, approximately 1 foot wide and deep within the access road.



Photo 5: View of erosional channel on the access road near the well pad entrance.