

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2017

Submitted Date:

08/31/2017

Document Number:

689500155**FIELD INSPECTION FORM**

Loc ID 315133 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230313	WELL	SI	03/01/2017	OW	103-07973	UNION PACIFIC 101 X 20	TA

General Comment:On location to witness MIT - form 42 doc # 401385733

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action: _____ Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230313	Type:	WELL	API Number:	103-07973	Status:	SI	Insp. Status:	TA
Workover									
Comment:	<div>On location to witness MIT - form 42 doc # 401385733 Top of packer @ 5801', top of perms @ 5852' = 51' Tubing pressure start - 0 psi/ finish - 0psi Intitial starting pressure 400 psi 5 min - 400 psi 10 min - 400 psi 15 min - 400 psi Final - 400 psi NO psi change</div>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass					

Comment:

No sediment flow evident

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT