

Construction and Stormwater Inspection

August 30, 2017

Operator: NOBLE ENERGY INC- #100322

Location ID: 450616

Weld County, CO

NWNW Section 11 T2N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Y11-29/Pad
Location ID: 450616



Photo 1. Photo taken from the northeast location, facing South. Operator has installed surface roughening around the perimeter of the location. Equipment traffic appears to have traveled over the BMP. BMPs need to be maintained to ensure the BMP is properly functioning.



Photo 2. Photo taken from the southeast location, facing South. Operator has installed surface roughening around the perimeter of the location. Equipment traffic (tractor-scraper) traveling over BMP. BMPs need to be maintained to ensure the BMP is properly functioning.

Inspection Photos
Location Name: Y11-29/Pad
Location ID: 450616



Photo 3. Photo taken from the southeast location, facing West. Operator has installed surface roughening around the perimeter of the location.



Photo 4. Photo taken from the southwest location, facing North. Operator has installed surface roughening around the perimeter of the location. Equipment traffic appears to have traveled over the BMP. BMPs need to be maintained to ensure the BMP is properly functioning.