



**Photo 1: View of the project area from the southeastern corner facing center.**



**Photo 2: View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and dropseed (*Sporobolus* sp.). Musk thistles appear to be treated.**



**Photo 3: View of the eastern portion of the project area from the southeastern corner of the well pad facing northward.**



**Photo 4: View of metal pipe in the northwestern corner of the well pad.**