

Inspection Photos
Location Name: Baxter Pass 11-7
Location ID: 323920



Photo 1. Tank labeled as permanently closed.



Photo 2. Wellhead not connected.