

Inspection Photos
Location Name: Young 11-14
Location ID: 322475



Photo 1. Vegetation around equipment.



Photo 2. Vegetation in pit/ tank containment.