

Inspection Photos
Location Name: HSR-Selby 7-32
API: 05-123-19290



Wellhead looking west



Wellhead looking west from lease road. In active crops

Inspection Photos
Location Name: HSR-Selby 7-32
API: 05-123-19290



Tank battery looking north



2" steel marked active riser north side of ECD

Inspection Photos
Location Name: HSR-Selby 7-32
API: 05-123-19290



3-2" steel marked active risers east side of separator



Unused disconnected meter run west of separator

Inspection Photos
Location Name: HSR-Selby 7-32
API: 05-123-19290



Battery looking northwest

