



BRG: 263.5° LAT: 40.431793 LON: -104.784679

08 Sep 2017, 13:34

Close view of area where nipple failed.

Location Number: 434391



Threaded outlet on compressor outlet where nipple failed.

Location Number: 434391



Close view of failed nipple.  
Location Number: 434391



**BRG: 177.6° LAT: 40.431895 LON: -104.784644**



**Emission Control Burners.**

Location Number: 434391



**BRG: 176.2° LAT: 40.431889 LON: -104.784641**



08 Sep 2017, 13:47

Heated horizontal separators and small compressors.

Location Number: 434391



**BRG: 187.0° LAT: 40.431886 LON: -104.784637**



08 Sep 2017, 13:47

**Tank Battery**  
Location Number: 434391



**BRG: 229.4° LAT: 40.431874 LON: -104.784634**



08 Sep 2017, 13:47

### Wells

Location Number: 434391



**BRG: 106.9° LAT: 40.431993 LON: -104.784563**



**Compressor installation where part failure occurred.**

Location Number: 434391