

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2017

Submitted Date:

09/08/2017

Document Number:

690000380

### FIELD INSPECTION FORM

Loc ID 434391 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Precup, Jim		james.precup@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Peterson, Tom		tom.peterson@state.co.us	
Pennington, Dave		dpennington@syrginfo.com	<a href="#">All Inspections</a>
Dewey, Terry		tdewey@syrginfo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434385	WELL	PR	03/31/2016	OW	123-38133	Kelly Farms 22-4-3CHZ	PR
434386	WELL	PR	03/31/2016	OW	123-38134	Kelly Farms 12-4-3CHZ	PR
434388	WELL	PR	03/31/2016	OW	123-38136	Kelly Farms A-4-3NHZ	PR
434390	WELL	PR	03/31/2016	OW	123-38138	Kelly Farms A-4-3CHZ	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		

Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 6		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 6		
Comment:	1 Compressor supplies pressure to valves. 2 Large compressors (~500 HP) 3 Smaller compressors (Sound barrier on east and south sides)		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLS	STEEL AST		40.431450,-104.784010
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 434385 Type: WELL API Number: 123-38133 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 434386 Type: WELL API Number: 123-38134 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 434388 Type: WELL API Number: 123-38136 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 434390 Type: WELL API Number: 123-38138 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>Inspection conducted in response to refferal from Greeley Fire Department.                      Location is situated just to the east of high school property line.                      Facility features a gas reinjection process that utilizes large compressors. A small (1/4 Dia) nipple on the compressor side of the outlet valve failed allowing the temporary loss of pressure through the small orifice resulting in a load piercing sound that led the the shutting in of the battery.                      Operator is conducting a study to identify and cause and develop an alternative approach to reduce the chance of any reoccurrence.                      Operator representatives on location at time of inspection include: Terry Dewey, Production Super and Bert Williams Safety Supervisor.                      Photos attached.</p>	carlilec	09/08/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690000381	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247406">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4247406</a>