

- Mason #2-4
- 5-067-08557



Photo 1: Wellhead sign. Previous inspection.

- Mason #2-4
- 5-067-08557



Photo 2: Wellhead sign.

- Mason #2-4
- 5-067-08557



Photo 3: Downed anchor marker. Previous inspection.

- Mason #2-4
- 5-067-08557



Photo 4: Repaired anchor marker.

- Mason #2-4
- 5-067-08557



Photo 5: Produced water tank with signs and labels not visible from outside containment berms. Previous inspection.

- Mason #2-4
- 5-067-08557



Photo 6: Produced water tank with signs and labels visible.

- Mason #2-4
- 5-067-08557



Photo 7: 1" riser to the right of production tank behind power panel. Valve not tagged or locked out.

- Mason #2-4
- 5-067-08557



Photo 8: Risers abandoned.

- Mason #2-4
- 5-067-08557



Photo 9: Two 1" risers at wellhead. Valve not tagged or locked out. Previous inspection.

- Mason #2-4
- 5-067-08557



Photo 10: Risers abandoned.