

Stormwater Inspection

September 7, 2017

Operator: RENEGADE OIL & GAS COMPANY LLC- #74165

Location ID: 319860

Adams County, CO

NWNW Section 20 T2S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 1. Photo taken September 7, 2017 from the entrance of the tank battery location, facing South. Appears the Operator has made repairs but has not installed a BMP.



Photo 2. Photo taken August 11, 2017 from the previous photo location, facing South. Stormwater erosion evident as an erosion channel funnels around the northern battery location and continues off location into the adjacent cropland.

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 3. Photo taken September 7, 2017 from the eastern tank battery location, facing West. Appears the Operator has made repairs but has not installed a BMP.



Photo 4. Photo taken August 11, 2017 from the previous photo location, facing West. Gully erosion observed from the previous inspection.

Inspection Photos
Location Name: Smith/Halverson Tank Battery
Location ID: 319860



Photo 5. Photo taken September 7, 2017 from the western tank battery location, facing North. Appears the Operator has made repairs but has not installed a BMP.