

Photo#1:
View North over Location



Photo#2:
View NW from Access Road leading into Location.



August 31, 2017

Photo#3:

Photo#4:

Site does not appear to have been completely recontoured.



August 31, 2017

Photo#5:

Large areas remain bare ground or populated only by Halogeton or Cheat grass.

Photo#6:



August 31, 2017

Photo#7:
On Location
Concrete Waste Pile



Photo#8:
Ground Rod ?



August 31, 2017

Photo#9:

Desirable grasses are struggling to establish in parts of Location.



Photo#10:



August 31, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayswater PA Emerald 279 API#103-09161