

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo from prior inspection for comparison



Photo 1: Weeds in tank battery

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo from prior inspection for comparison



Photo 2: Stained soil removed or remediated

Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



Photo from prior inspection for comparison



Photo 3: Stained soil removed or remediated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



Photo from prior inspection for comparison



Photo 4: Stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo from prior inspection for comparison



Photo 5: Seeds controlled around ECDs

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo from prior inspection for comparison



Photo 6: Stained soil at compressor removed.

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo from prior inspection for comparison



Photo 7: Stained soil, oil in cellar.

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo 8: Stained soil around wellhead



Photo 9: Stained soil at power unit

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo 10: Unused equipment around wellheads



Photo 11: Unused equipment around wellheads

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Photo 12: Unused equipment at compressors



Photo 13: Cut weeds around separators

Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



Photo 14: Cut weed debris around separators



Photo 15: Unused equipment at tank battery

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Fire picture



Fire picture

Inspection Photos
Location Name: Spaur Brothers North Pad 31-219HN
API: 05-123-38693



Fire picture



Fire picture

Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



Fire picture



Fire picture



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources