

Location

Lease Road:			
Type	Access		
comment:	Two track through CRP		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292333 Type: WELL API Number: 125-10975 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Day 33-35 & 43-35\) 1775' NNE on west side of CR N](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT