

Location			
Lease Road:			
Type	Access		
comment:	Two track through CRP		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease signs for associated wells mounted to metal shed		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 2		corrective date
Comment:	Shared meter run for Day 12-35 & 14-35		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:	Jensen unit	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 292334 Type: WELL API Number: 125-10974 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Day 12-35 & 14-35\) 590' NW on east side of CR M](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT