



IMAGE COURTESY OF ESRI

LEGEND

- MONITORING WELL
- DESTROYED MONITORING WELL
- REMOVED FROM MONITORING PROGRAM
- WELLHEAD
- SURVEYED GROUNDWATER FLOW DIRECTION
- FENCE
- RELATIVE GROUNDWATER ELEVATION CONTOUR
CONTOUR INTERVAL = 0.50 FEET
GRADIENT = 0.02 FEET/FOOT
- EXCAVATION EXTENT
- BERM

GROUNDWATER ELEVATIONS WERE MEASURED ON APRIL 10, 2017.
NM: NOT MEASURED




FIGURE 2
GROUNDWATER ELEVATION CONTOUR MAP
 EDWARDS WILLIAM GU #1
 SESW SEC 26-T3N-R68W
 WELD COUNTY, COLORADO
 KERR-MCGEE OIL & GAS ONSHORE LP

