

Construction and Stormwater Inspection

September 7, 2017

Operator: BISON EXPLORATION LLC - #10646

Location ID: 451389

Arapahoe County, CO

SENE Section 22 T4S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Houlihan
Location ID: 451389



Photo 1. Photo taken from the entrance of location, facing North. Topsoil stockpile has been temporarily stabilized with equipment. Operator was IN-PROCESS of making adjustments to the location so BMPs would be re-installed later that day or the next. Operator indicated there was a ditch BMP along the entire location perimeter.



Photo 2. Photo taken from the northeastern location, facing East. Retention pond under construction for the permanent stormwater control BMP.

Inspection Photos
Location Name: Houlihan
Location ID: 451389



Photo 3. Photo taken from the northern location, facing East. Ditch BMP has been installed along the well pad perimeter.



Photo 4. Photo taken from the western location, facing North. Operator was IN-PROCESS of making adjustments to the location so BMPs would be re-installed later that day or the next. Operator indicated there was a ditch BMP along the entire location perimeter.

Inspection Photos
Location Name: Houlihan
Location ID: 451389



Photo 5. Photo taken from the southwestern location, facing Southeast. Retention pond under construction for the permanent stormwater control BMP.



Photo 6. Photo taken from the southern location, facing East. Operator was IN-PROCESS of making adjustments to the location so BMPs would be re-installed later that day or the next. Operator indicated there was a ditch BMP along the entire location perimeter.