

Photo#1:  
View North over Location.



Photo#2:  
View West over Well head.



August 31, 2017


Photo#3:

Tanks on Location



Photo#4:

Staining, leak from pipe at base of Tank.



August 31, 2017