

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2017

Submitted Date:

09/11/2017

Document Number:

666803618**FIELD INSPECTION FORM**

Loc ID 334907 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256072	WELL	PR	09/14/1999	GW	045-07427	COUEY 8-16 (18E)	PR
258256	WELL	PR	03/31/2000	GW	045-07526	COUEY 8-9 (I8E)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:					Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
METHANOL		1	OTHER	STEEL AST				,		
Comment:		Centralized battery								

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.458049,-107.683891
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 256072 Type: WELL API Number: 045-07427 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 258256 Type: WELL API Number: 045-07526 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Seeding	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT