

Construction and Stormwater Inspection

September 8, 2017

Operator: CRESCENT POINT ENERGY U.S. CORP - #10520

Location ID: 447902

Weld County, CO

NENW Section 31 T9N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shull Pad
Location ID: 447902



Photo 1. Photo taken from the southern location, facing Northeast. Construction operations still underway. South and west fill slopes appear to be temporarily stabilized even though equipment has not properly tracked perpendicular to the slope. Water truck at location mitigating fugitive dust from operations.



Photo 2. Photo taken from the southern location, facing North. Construction operations still underway. South and west fill slopes appear to be temporarily stabilized even though equipment has not properly tracked perpendicular to the slope.

Inspection Photos
Location Name: Shull Pad
Location ID: 447902



Photo 3. Photo taken from the southern location, facing Northwest. Construction operations still underway. South and west fill slopes appear to be temporarily stabilized even though equipment has not properly tracked perpendicular to the slope.



Photo 4. Photo taken from the western location, facing South. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.