

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2017

Submitted Date:

09/12/2017

Document Number:

680401851**FIELD INSPECTION FORM**Loc ID 324466 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 922 EAST 2ND AVENUECity: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,	970-385-0696	inspection@sginterests.com	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211720	WELL	PR	06/12/2012	GW	051-06042	JACOBS 29-1	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 1	
Comment:	Inside tank berms	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Transfer pump in housing, inside tank berms.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	200 BBLS	HEATED STEEL AST		39.076245,-107.367860
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	211720	Type:	WELL	API Number:	051-06042	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Flowing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT