

Inspection Photos
Location Name: Raisley 11-34
API: 05-123-13317



Southeast edge of location looking north. Erosion issues have been addressed. Weeds have been controlled



Southwest edge of location looking north. Erosion issues have been addressed, berm constructed on north/northwest edge of location