

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2017

Submitted Date:

09/12/2017

Document Number:

666803675

FIELD INSPECTION FORM

Loc ID 335162 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290772	WELL	PR	12/05/2007	GW	045-14197	SPECIALTY 11C-28-692	PR
291037	WELL	PR	12/04/2007	GW	045-14264	SPECIALTY 11B-28-692	PR
291038	WELL	PR	12/24/2007	GW	045-14263	SPECIALTY 11A-28-692	PR
291334	WELL	PR	12/05/2007	GW	045-14331	SPECIALTY 11D-28-692	PR

General Comment:

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>290772</u>	Type:	<u>WELL</u>	API Number:	<u>045-14197</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>291037</u>	Type:	<u>WELL</u>	API Number:	<u>045-14264</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>291038</u>	Type:	<u>WELL</u>	API Number:	<u>045-14263</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>291334</u>	Type:	<u>WELL</u>	API Number:	<u>045-14331</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
		Ditches	Pass			
Gravel	Pass					
		Rip Rap	Pass			
Seeding	In Process					
		Check Dams	Pass			
Ditches	Pass					
Berms	Pass					
		Sediment Traps	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT