



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), crested wheatgrass (*Agropyron intermedium*), and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of erosional channels in the northern portion of the project area.



Photo 4: View of the eastern portion of the project area from the southeastern edge facing northward. Sparse vegetation, rilling, and sediment deposition are occurring.