

Inspection Photos
Location Name: Simoes 22-30
API: 05-081-07724



Photo 1. Overview of location taken at entrance facing southeast. Weeds visible in foreground, unused equipment storage in background.



Photo 2. No wellhead sign.