

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/25/2017

Submitted Date:
09/15/2017

Document Number:
689700197

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335574 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

28 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282307	WELL	PR	03/28/2007	GW	045-11718	N. PARACHUTE EF12B-22 D27595	PR
282308	WELL	PR	05/09/2008	GW	045-11719	N. PARACHUTE EF05D- 22D27 595	PR
282309	WELL	PR	03/28/2007	GW	045-11720	N.PARACHTE EF11B-22 D27 59	PR
282310	WELL	PR	03/28/2007	GW	045-11721	N. PARACHUTE EF09B- 21D27 595	PR
282311	WELL	PR	03/28/2007	GW	045-11722	N.PARACHUTE EF06D-22- D27 59	PR
282312	WELL	PR	05/11/2008	GW	045-11723	N. PARACHUTE EF05B- 22D27595	PR
282313	WELL	PR	03/28/2007	GW	045-11724	N. PARACHUTE EF11D-22 -D27 59	PR
282314	WELL	PR	03/28/2007	GW	045-11728	N.PARACHUTE EF06B-22 D27 59	PR
282315	WELL	PR	03/28/2007	GW	045-11729	N.PARACHUTE EF09B-22 D27 59	PR
282316	WELL	PR	03/28/2007	GW	045-11730	N.PARACHUTE EF14B-22 D27 59	PR
282317	WELL	PR	03/28/2007	GW	045-11731	N PARACHUTE EF10B22 D27 595	PR
282318	WELL	PR	03/28/2007	GW	045-11732	N. PARACHUTE EF10D-22 D27 59	PR
282334	WELL	PR	08/12/2008	GW	045-11748	N. PARACHUTE EF14B D27 595	PR
282335	WELL	PR	11/26/2008	GW	045-11747	N.PARACHUTE EF 12B D27 595	PR
282336	WELL	PR	02/01/2014	GW	045-11746	N. PARACHUTE EF13B D27 595	PR
282338	WELL	PR	08/01/2008	GW	045-11745	N. PARACHUTE EF11B D27 595	PR

282339	WELL	PR	12/01/2008	GW	045-11744	N.PARACHUTE EF 16B-28 D27 5	PR
282340	WELL	PR	12/01/2008	GW	045-11743	N. PARACHUTE EF05B D27 595	PR
282545	WELL	PR	12/09/2008	GW	045-11778	N. PARACHUTE EF08D-28 D27 59	PR
282546	WELL	PR	12/05/2008	GW	045-11779	N. PARACHUTE EF05A-27 D27 59	PR
282547	WELL	PR	01/27/2014	GW	045-11780	N. PARACHUTE EF09D-28 D27 59	PR
282556	WELL	PR	02/01/2014	GW	045-11790	N. PARACHUTE EF09B-28 D27 59	PR
282557	WELL	PR	12/05/2008	GW	045-11791	N. PARACHUTE EF13A-27 D27 59	PR
282923	WELL	PR	08/10/2008	GW	045-11866	N. PARACHUTE EF12D D27 595	PR
291335	WELL	PR	07/10/2007	GW	045-14332	N.PARACHUTE EF03B D27 595	PR
291336	WELL	PR	07/10/2007	GW	045-14333	N.PARACHUTE EF04D D27 595	PR
291337	WELL	PR	07/10/2007	GW	045-14334	N.PARACHUTE EF02B D27 595	PR
291338	WELL	PR	07/10/2007	GW	045-14335	N.PARACHUTE EF 15B-22 D27 5	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282307	Type:	WELL	API Number:	045-11718	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282308	Type:	WELL	API Number:	045-11719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282309	Type:	WELL	API Number:	045-11720	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282310	Type:	WELL	API Number:	045-11721	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282311	Type:	WELL	API Number:	045-11722	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282312	Type:	WELL	API Number:	045-11723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282313	Type:	WELL	API Number:	045-11724	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282314	Type:	WELL	API Number:	045-11728	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 282315	Type: WELL	API Number: 045-11729	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282316	Type: WELL	API Number: 045-11730	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282317	Type: WELL	API Number: 045-11731	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282318	Type: WELL	API Number: 045-11732	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282334	Type: WELL	API Number: 045-11748	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282335	Type: WELL	API Number: 045-11747	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282336	Type: WELL	API Number: 045-11746	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 282338	Type: WELL	API Number: 045-11745	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 282339	Type: WELL	API Number: 045-11744	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 282340	Type: WELL	API Number: 045-11743	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
Facility ID: 282545	Type: WELL	API Number: 045-11778	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 282546	Type: WELL	API Number: 045-11779	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 282547	Type: WELL	API Number: 045-11780	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 282556	Type: WELL	API Number: 045-11790	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 282557	Type: WELL	API Number: 045-11791	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 282923	Type: WELL	API Number: 045-11866	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	

Facility ID: <u>291335</u>	Type: <u>WELL</u>	API Number: <u>045-14332</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Producing well</u>			
Corrective Action:			Date:	
Facility ID: <u>291336</u>	Type: <u>WELL</u>	API Number: <u>045-14333</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Producing well</u>			
Corrective Action:			Date:	
Facility ID: <u>291337</u>	Type: <u>WELL</u>	API Number: <u>045-14334</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Producing well</u>			
Corrective Action:			Date:	
Facility ID: <u>291338</u>	Type: <u>WELL</u>	API Number: <u>045-14335</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Producing well</u>			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689700289	EF06D J27 595 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4252326