

**Inspection Photos**  
**Location Name: Tsuzuki 3**  
**API: 05-001-06852**



**Wellhead, pumping unit, and prime mover**



**Wellhead detail, Tubing open, casing closed, casing backside tied into 1" buried line.**

Inspection Photos  
Location Name: Tsuzuki 3  
API: 05-001-06852



Wellhead signage detail



1" unidentified line east of prime mover