

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2017

Submitted Date:

09/15/2017

Document Number:

680401868

FIELD INSPECTION FORM

Loc ID 324474 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 922 EAST 2ND AVENUE
City: DURANGO State: CO Zip: 81301

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, '	970-385-0696	inspection@sginterests.com	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276683	WELL	PR	08/01/2012	GW	051-06062	MCINTYRE 11-90-14 1	PR

General Comment:

Empty text area for general comments.

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		39.099689,-107.419791
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 276683 Type: WELL API Number: 051-06062 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Self Inspection	Pass	
Gravel	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT