

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2017

Submitted Date:

09/15/2017

Document Number:

680401877**FIELD INSPECTION FORM**Loc ID 324473 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 922 EAST 2ND AVENUECity: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,	970-385-0696	inspection@sginterests.com	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276658	WELL	XX	11/01/2016	GW	051-06061	FALCON SEABOARD 11-90-11 2	TA

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Pump Jack	# 0		
Comment:	Equipment removed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Equipment removed		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 0		
Comment:	Equipment removed		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	0				
Comment:	Tanks and berms removed				

Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	276658	Type:	WELL	API Number:	051-06061	Status:	XX	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: <input type="text" value="Last MIT 4/18/2014"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT