



Location					
<b>Lease Road:</b>					
Type	Main				
comment:					
Corrective ActionL			Date:		
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:					
Corrective Action:			Date:		
<b>Emergency Contact Number:</b>					
Comment:	OK			Date:	
Corrective Action:			Date:		
Overall Good: <input checked="" type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	ROD IRON FENCE				
Corrective Action:			Date:		
<b>Equipment:</b>					
Type: Plunger Lift	# 1			corrective date	
Comment:	INTERMITTER CONTROLLER ON WELLHEAD				
Corrective Action:			Date:		
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
<b>Flaring:</b>					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:			Date:		

**Inspected Facilities**

Facility ID: 273708 Type: WELL API Number: 001-09519 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Comment:

OK  
 BRADEN TEST START 12 PSI AND WATER, 5 MIN O NO WATER, 10 MIN 0, 15 MIN  
 O, 20 MIN 0, 25 MIN 0, 30 MIN 0, PASSED  
 TBG START 545 PSI, 5 MIN 545 PSI, 10 MIN 545 PSI 15 MIN 545 PSI, 20 MIN 545 PSI,  
 25 MIN 545 PSI, 30 MIN 545 PSI  
 CSG START 600 PSI, 5 MIN 600 PSI, 10 MIN 600 PSI, 15 MIN 600 PSI, 20 MIN 600 PSI,  
 25 MIN 600 PSI, 30 MIN 600 PSI

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass  
Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>						Date: _____
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

<u>COGCC Comments</u>		
Comment	User	Date
BRADENHEAD TEST	montoyaj	09/15/2017