

- Allison Unit 59
- 05-067-06145




Photo 1: Wellhead sign.

- Allison Unit 59
- 05-067-06145



Photo 2: Unused equipment under separator.

- Allison Unit 59
- 05-067-06145



**Photo 3: Unused equipment beside meter run shed.**

- Allison Unit 59
- 05-067-06145



**Photo 4: Steel cable beside power pole anchor.**

- Allison Unit 59
- 05-067-06145



**Photo 5: Unmarked deadman.**

- Allison Unit 59
- 05-067-06145



**Photo 6: Vehicle ruts on location.**

- Allison Unit 59
- 05-067-06145



Photo 7: 4" steel riser NW of gas meter run shed .

- Allison Unit 59
- 05-067-06145



Photo 8: Group of (3) steel risers N side of meter run shed.

- Allison Unit 59
- 05-067-06145



**Photo 9: Closer view of group of (3) risers N side of meter run shed.**

- Allison Unit 59
- 05-067-06145



**Photo 10: Unused risers on W side of meter run shed.**