

Photo#1:

View over Location to NE. Arrow indicates PA Marker for API#103-01074



September 1, 2017

Inspection Photos: Chevron PA Sharples- McLaughlin API#103-01074

Photos #2&3: Before

Unknown Facilities located Below & East of Location.



September 1, 2017

Inspection Photos: Chevron PA Sharples- Mclaughin API#103-01074

Photo#4: After
Lower area has been reclaimed



September 1, 2017

Inspection Photos: Chevron PA Sharples- McLaughlin API#103-01074

Photo#5: Before

Pipe Risers at base of Upper Loc.



Photo#6: After

Area has been Reclaimed.



Photo#7: Before

Drain area exiting Location



Photo#8: After



September 1, 2017

Inspection Photos: Chevron PA Sharples- Mclaughin API#103-01074