

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Facility sign near tank battery, stained crude oil tank in background, on right.



Tank battery sign.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Approximate area of Spill/Release Point ID #449895.



Island Butte B tank battery.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Island Butte B manifold.



Dead and/or dying trees along facility perimeter.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Facility separators and treaters.



Meter runs, treaters, and separators

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Island Butte B water well sign.



Island Butte B well head.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Leaking chemical injection fittings.



Unused spool north of Island Butte B water well.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Fenced pit area.



Open topped fiberglass tank inside pit.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



Wildlife netting on fiberglass tank.



Secondary containment for fuel container.

Inspection Photos
Location Name: Island Butte B
Facility ID: 452204



400 bbl. fresh water AST.



Pump house.