

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2017

Submitted Date:

09/18/2017

Document Number:

666803685

### FIELD INSPECTION FORM

Loc ID 335147 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286319	WELL	PR	12/31/2006	GW	045-12642	SPECIALTY 12C-28-692	PR
286348	WELL	PR	12/27/2006	GW	045-12645	SPECIALTY 22C-28-692	PR
286349	WELL	PR	01/05/2007	GW	045-12644	SPECIALTY 12A-28-692	PR
286350	WELL	PR	12/28/2006	GW	045-12643	SPECIALTY 22A-28-692	PR
412834	WELL	PR	03/17/2010	GW	045-18650	SPECIALTY 22B-28-692	PR
412835	WELL	PR	03/17/2010	GW	045-18649	SPECIALTY 12D-28-692	PR
412836	WELL	PR	03/17/2010	GW	045-18648	SPECIALTY 22D-28-692	PR
412837	WELL	PR	03/19/2010	GW	045-18647	SPECIALTY 12B-28-692	PR

**General Comment:**

[Tank battery about 500 feet southwest of well. Battery Id. 16816 is central tank battery for 5 wells. Porter Fed. 11-28,13-28,12-28 & Specialty Fed 13C-28,14D-28](#)



<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	286319	Type:	WELL	API Number:	045-12642	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	286348	Type:	WELL	API Number:	045-12645	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	286349	Type:	WELL	API Number:	045-12644	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	286350	Type:	WELL	API Number:	045-12643	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412834	Type:	WELL	API Number:	045-18650	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412835	Type:	WELL	API Number:	045-18649	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412836	Type:	WELL	API Number:	045-18648	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	412837	Type:	WELL	API Number:	045-18647	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				



**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
Berms	Pass					
Ditches	Pass					
		Gravel	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT