

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2017

Submitted Date:

09/18/2017

Document Number:

666803686**FIELD INSPECTION FORM**Loc ID 324130 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258526	WELL	PR	09/01/2004	GW	045-07642	PORTER FEDERAL 11-28	PR

**General Comment:**

Tank battery about 500 feet southwest of well. Battery Id. 16816 is central tank battery for 5 wells. Porter Fed. 11-28, 13-28, 12-28 & Specialty Fed 13C-28, 14D-28

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 5

Comment: Corrective Action: Date: 

Type: Emission Control Device

# 1

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 3

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 1

Comment: Corrective Action: Date: 

Type: Pig Station

# 1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	200 BBLS	STEEL AST		39.495160,107.675320	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	258526	Type:	WELL	API Number:	045-07642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:								Date:	

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Rip Rap	Pass			
Seeding	Pass					
Gravel	Pass					
		Gravel	Pass			
		Culverts	Pass			
		Check Dams	Pass			
		Sediment Traps	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT