

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2017

Submitted Date:

09/18/2017

Document Number:

666803687

### FIELD INSPECTION FORM

Loc ID 335347 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

- 4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259147	WELL	PR	09/01/2004	GW	045-07695	JACKSON 10-28	PR
259438	WELL	PR	09/01/2004	GW	045-07727	JACKSON 9-28	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	200 BBLs	STEEL AST		39.496407,-107.668941
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 259147 Type: WELL API Number: 045-07695 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 259438 Type: WELL API Number: 045-07727 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
		Sediment Traps	Pass			
Gravel	Pass					
		Check Dams	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT