

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2017

Submitted Date:

09/18/2017

Document Number:

687900342**FIELD INSPECTION FORM**
 Loc ID 309436 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295025	WELL	PR	06/16/2008	GW	071-09531	HILL RANCH 36-11	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0	OTHER	OTHER		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0	OTHER	OTHER		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0	OTHER	OTHER		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No						
Comment:						
Corrective Action:					Date:	

Flaring:

Type					
Comment:					
Corrective Action:					



Inspected Facilities									
Facility ID:	295025	Type:	WELL	API Number:	071-09531	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70'

Corrective Action

Date:

Monitoring:

Monitoring Type

Comment`

Chain

Yellow

COGCC Comments

Comment

User

Date

There are no tanks and only 1 production pit.

duranj

09/18/2017