

Inspection Photos

9/13/2017

Operator: MURFIN DRILLING COMPANY INC -
61650

Location ID: 450166

Inspection Doc. Number: 682502559
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 450166



Photo 1: Photo taken from at the access road and country road. Photo shows rock had been placed as a vehicle tracking BMP.



Photo 2: Photo taken from the northwest corner of the location, facing east. Photo shows stormwater and sediment control BMPs missing. Note: upon the arrival of inspector, the contractor constructing the location began to install surface roughening along the perimeter of the location. Stormwater and sediment control BMPs need to be installed prior to construction activities.

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 450166



Photo 3: Photo taken from the northwest corner of the location, facing south. Photo shows stormwater and sediment control BMPs missing. Note: upon the arrival of inspector, the contractor constructing the location began to install surface roughening along the perimeter of the location. Stormwater and sediment control BMPs need to be installed prior to construction activities.



Photo 4: Photo taken from the west end of the location, facing west. Photo shows contractor constructing the location installing surface roughening along the perimeter of the location. Stormwater and sediment control BMPs need to be installed prior to construction activities.

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 450166



Photo 5: Photo taken from the southwest end of the location, facing north.



Photo 6: Photo taken from the southwest end of the location, facing west.

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 450166



Photo 7: Photo taken from the southeast end of the location, facing west.



Photo 8: Photo taken from the southeast end of the location, facing north.

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 450166



Photo 9: Photo taken from the northeast end of the location, facing west.



Photo 10: Photo taken from the northeast end of the location, facing south.