

Inspection Photos

9/18/2017

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 319767

Inspection Doc. Number: 682502577
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 2: Photo taken from the former battery location. Photo shows weeds have not been managed per CAs



Photo 3: Photo taken from the former battery location. Photo shows weeds have not been managed per CAs