

Final Reclamation and Stormwater Inspection

September 13, 2017

Operator: NGL WATER SOLUTIONS DJ LLC - 10373

API: 05-123-16804

Weld County, CO

SESE Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CONQUEST SWD #1-8
API: 05-123-16804



Photo 1. Photo taken from an access road off CR 53, facing East. Access road is no longer in use per Weld County requirements as described by an Operator representative. Access road will have to be reclaimed per Rule 1004.



Photo 2. Photo taken from an access road off CR 53, facing West. Access road is no longer in use per Weld County requirements as described by an Operator representative. Access road will have to be reclaimed per Rule 1004.

Inspection Photos
Location Name: CONQUEST SWD #1-8
API: 05-123-16804



Photo 3. Photo taken from the eastern reclamation area, facing West. Bare patches with little to no germination were observed throughout the reclamation area. Germination is not uniform throughout the reclamation area and was mostly dominated by Russian thistle, an annual undesirable weed. Most of the green foliage in the photo is that of Russian thistle.



Photo 4. Photo taken from the approximate central reclamation area, facing West. Photo illustrates little to no germination throughout the reclamation area. Most of the green foliage in the photo is that of Russian thistle.

Inspection Photos
Location Name: CONQUEST SWD #1-8
API: 05-123-16804



Photo 5. Close up photo taken from the previous photo location. Photo illustrates no to little germination. The green foliage in the photo is that of Russian thistle.



Photo 6. Photo taken from the south-central reclamation area, facing North. Photo illustrates little to no germination throughout the reclamation area.

Inspection Photos
Location Name: CONQUEST SWD #1-8
API: 05-123-16804



Photo 7. Photo taken from the western reclamation area, facing West. Photo illustrates a patch of desirable vegetative growth mixed with Russian thistle.



Photo 8. Photo taken from the western reclamation area, facing East. Photo illustrates a portion of desirable germination establishment but not uniform.

Inspection Photos
Location Name: CONQUEST SWD #1-8
API: 05-123-16804



Photo 9. Reference photo taken just west of the western reclamation area. This location was recently mowed but illustrates the vegetative growth that is not reflective throughout the reclamation area.