

Final Reclamation and Stormwater Inspection

September 13, 2017

Operator: BARRETT CORPORATION* BILL- 10071

API: 05-123-23966

Weld County, CO

SENW Section 3 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: 70 RANCH #22-3
API: 05-123-23966



Photo 1. Photo taken from the approximate center of the location, facing North. Little to no germination of desirable species was observed throughout most of the reclamation area. Operator may need to perform additional reclamation activities in the future if the location does show more germination establishment. Active prairie dog colony observed throughout the adjacent areas.



Photo 2. Photo taken from the approximate center of the location, facing East. Little to no germination of desirable species was observed throughout most of the reclamation area. Operator may need to perform additional reclamation activities in the future if the location does show more germination establishment.

Inspection Photos
Location Name: 70 RANCH #22-3
API: 05-123-23966



Photo 3. Photo taken from the approximate center of the location, facing South. Little to no germination of desirable species was observed throughout most of the reclamation area. Operator may need to perform additional reclamation activities in the future if the location does show more germination establishment.



Photo 4. Photo taken from the approximate center of the location, facing West. Little to no germination of desirable species was observed throughout most of the reclamation area. Operator may need to perform additional reclamation activities in the future if the location does show more germination establishment.

Inspection Photos
Location Name: 70 RANCH #22-3
API: 05-123-23966



Photo 5. Reference photo taken just south of the reclamation area, facing South. Photo illustrates the vegetative growth in the reference area is not reflective throughout the reclamation area.