

Inspection Photos

Location Name: NC Farms 9,10,15,16 & 20-32

Location ID: 426843



Wellheads looking east



NC Farms 16-32...stained soil under master valve



Inspection Photos
Location Name: NC Farms 9,10,15,16 & 20-32
Location ID: 426843



Battery looking west



Stained soil around compressor skid