

Inspection Photos
Location Name: Miller 43-29
API #: 05-123-20223
Location ID: 331141



Wellheads looking west, weeds need to be controlled



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources