

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2017

Submitted Date:

09/20/2017

Document Number:

682402784**FIELD INSPECTION FORM**
 Loc ID 427917 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		<u>ecreed@gwogco.com</u>	<u>Principal Agent</u>

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427723	WELL	DG	08/28/2017	LO	123-35099	Raindance FC 23-369HN	CI
427727	WELL	DG	08/29/2017	LO	123-35100	Raindance FC 23-369HC	CI
432197	WELL	DG	08/30/2017	LO	123-37004	Raindance FC 26-032HC	CI
451091	WELL	DG	07/11/2017		123-44982	Raindance FD 20-362HN	CI
451093	WELL	DG	07/06/2017		123-44983	Raindance FD 20-282HN	CI
451094	WELL	DG	07/09/2017		123-44984	Raindance FD 20-322HN	CI
451097	WELL	DG	07/10/2017		123-44987	Raindance FD 20-362HNNX	CI
451098	WELL	DG	07/10/2017		123-44988	Raindance FD 20-359HC	CI
451099	WELL	DG	07/08/2017		123-44989	Raindance FD 20-319HN	CI
451101	WELL	DG	07/08/2017		123-44990	Raindance FD 20-319HNNX	CI
451102	WELL	DG	07/07/2017		123-44991	Raindance FD 20-282HC	CI
451103	WELL	DG	07/06/2017		123-44992	Raindance FD 20-242HN	CI
451168	WELL	DG	08/30/2017		123-45007	Raindance FC 26-369HC	CI
451715	WELL	DG	08/27/2017		123-45196	Raindance FD 20-399HC	CI

General Comment:This is a desktop follow-up inspection to Field Inspection Report Document # 682402764.

Location Construction

Location ID: 427917 CDP: _____

Comment: Form 42 Document #401409135 was received on September 20, 2017. Operator has performed the required corrective action.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID:	<u>427723</u>	Type:	<u>WELL</u>	API Number: <u>123-35099</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>427727</u>	Type:	<u>WELL</u>	API Number: <u>123-35100</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>432197</u>	Type:	<u>WELL</u>	API Number: <u>123-37004</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451091</u>	Type:	<u>WELL</u>	API Number: <u>123-44982</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451093</u>	Type:	<u>WELL</u>	API Number: <u>123-44983</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451094</u>	Type:	<u>WELL</u>	API Number: <u>123-44984</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451097</u>	Type:	<u>WELL</u>	API Number: <u>123-44987</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451098</u>	Type:	<u>WELL</u>	API Number: <u>123-44988</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451099</u>	Type:	<u>WELL</u>	API Number: <u>123-44989</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451101</u>	Type:	<u>WELL</u>	API Number: <u>123-44990</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451102</u>	Type:	<u>WELL</u>	API Number: <u>123-44991</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451103</u>	Type:	<u>WELL</u>	API Number: <u>123-44992</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451168</u>	Type:	<u>WELL</u>	API Number: <u>123-45007</u> Status: <u>DG</u> Insp. Status: <u>CI</u>
Facility ID:	<u>451715</u>	Type:	<u>WELL</u>	API Number: <u>123-45196</u> Status: <u>DG</u> Insp. Status: <u>CI</u>