

Inspection Photos
Location Name: Burroughs South Pad
API: 05-123-40736



Photo 1: Location, looking SE



Photo 2: Wellheads, looking SE

Inspection Photos
Location Name: Burroughs South Pad
API: 05-123-40736



Photo 3: Maintenance tank lacking placards, oil labeling.

