

Inspected Facilities

Facility ID: 432326 Type: WELL API Number: 123-37066 Status: SI Insp. Status: SI

Complaint

Comment: [Complaint #: 200443964](#)
[Field Inspector Assigned: C Pesicka](#)
[Well Number: 05- Location #: 432327](#)
[Inspection Document #: 684904412](#)
 Nature of complaint: [Sound](#)
 If Sound GPS Coordinates of Survey Location: [n/a](#)
 Inspection Observations:
 An inspection of the above location was conducted with focus sound. Speaking with Bayswater personnel, it was determined the site had been shut in at the time of the complaint. Emission control devices continued to run to deal with VOCs from production tanks.
 18A doc#: 200443975

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: [SI](#)

Corrective Action: _____ Date: _____

BradenHead

Comment: [Bradenhead plumbed to surface.](#)

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684904413	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4256053