

Form Information

---

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Sep 19, 2017 8:03:02 AM MDT
Server Receive Date:	Sep 19, 2017 8:03:09 AM MDT
Reference Number:	20170919-1866445623
Location:	Unknown Location

Information

---

Name	reclamationtablet
Date	Sep 18, 2017
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	Southeast
Well Name	SO UTE 32- 8; 1- 1 (MV)
API Number	50670520200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Completed work description

Collapsed erosion reels and installed erosion logs to prevent soil runoff.