

- Chevillar 32 - 32
- 05-067-09196



Photo 1: Wellhead sign.

- Chevillar 32 - 32
- 05-067-09196



Photo 2: Weeds around wellhead.

- Chevillar 32 - 32
- 05-067-09196



Photo 3: Produced water tank with peeling NFPA label and no capacity label.

- Chevillar 32 - 32
- 05-067-09196



Photo 4: Unused equipment and debris on left side of pump jack.

- Chevillar 32 - 32
- 05-067-09196



Photo 5: Unused equipment backside of pump jack.

- Chevillar 32 - 32
- 05-067-09196



Photo 6: Unused equipment on right side of pump jack.

- Chevillar 32 - 32
- 05-067-09196



Photo 7: Concrete cribbing in corner of location.

- Chevillar 32 - 32
- 05-067-09196



Photo 8: Debris inside separator and concrete blocks around front of separator.

- Chevillar 32 - 32
- 05-067-09196



Photo 9: View of weeds covering location

- Chevillar 32 - 32
- 05-067-09196



Photo 10: Weeds around fired equipment.

- Chevillar 32 - 32
- 05-067-09196



Photo 11: Weeds growing inside and on production tank battery berms.

- Chevillar 32 - 32
- 05-067-09196



Photo 12: Weeds growing in and on production tank battery berms from backside.

- Chevillar 32 - 32
- 05-067-09196



Photo 13: One of several animal burrow in tank battery berms.

- Chevillar 32 - 32
- 05-067-09196



Photo 14: Animal burrow in tank battery berms.