

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through pasture with cattle guard		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by cattle guard at entrance. Update to current operator		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank. Update to current operator		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around HGS, tank battery, unit and on access. Maintain weeds		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Pipe fence around HGS		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire panels around tank		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 261890 Type: WELL API Number: 099-06872 Status: PR Insp. Status: PR

Producing Well

Comment: [Well is SI at time of inspection](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT