

Inspection Photos

9/18/2017

Operator: PETRO-CANADA RESOURCES (USA)

INC - 72085

Location ID: 311664

Inspection Doc. Number: 682502567

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 1: Photo taken from the east end of the northern degradation area. Photo shows no stormwater management, or reclamation activities have been conducted per corrective actions and per FIU manager. See doc. #2227506



Photo 2: Photo taken from the east end of the northern degradation area. Photo shows no stormwater management, or reclamation activities have been conducted per corrective actions and per FIU manager. See doc. #2227506



Photo 3: Photo taken from the northern degradation area. Photo shows no stormwater management, or reclamation activities have been conducted per corrective actions and per FIU manager. See doc. #2227506



Photo 4: Photo taken from the northern degradation area. Photo shows pedestal formations occurring due to stormwater degradation. Pedestals form when stormwater (or wind erosion) erodes away un-stabilized areas of soil around vegetation.



Photo 5: Photo taken from the northern degradation area. Photo shows pedestal formations occurring due to stormwater degradation. Pedestals form when stormwater (or wind erosion) erodes away un-stabilized areas of soil around vegetation.